

In Situ Testing of Shallow Depth Helical Heat Exchangers for Ground Source Heat Pump Systems (OR-16-C044)

Detected error Dic-10-2015 would imply the following changes:

Heating Test

Figure 6 (Original)





Figure 6 (Corrected)



Cooling Test

Figure 7 (Original)





Figure 7 (Corrected)



It would also imply changing a few numbers in the text and in Table 1.