

Error #5

Page = 5

Location = Fourth bullet point in middle of page

What is currently stated: *Concerning the variable 24 hour load tests, the Mfr A controller generally yields greater savings for a similar differential, which monitors both return/supply temperatures where Mfr B monitors the return only.*

What should be stated: *Concerning the variable 24 hour load tests, the Mfr A controller generally yields greater savings for a similar differential, which monitors both return/supply temperatures where Mfr B monitors the ~~return~~ **supply** only.*